

AL-I-C-017
Athey Frame House
Off Rt. 51
Keifers, Maryland
Latter half 19th century

The Athey Frame House was a typical rural farm dwelling found in southeastern Allegany County. Its owner was a farmer who was part of a county-wide participation during the latter quarter of the 19th century. The house represents a transition in architecture for the Keifers area because it has stone pillars in the corners like the log houses in the area; yet it is a frame house.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Athey Frame House

AND/OR COMMON

2 LOCATION

STREET & NUMBER

Off Rt. 51

CITY, TOWN

Keifers

☒ VICINITY OF

CONGRESSIONAL DISTRICT

Sixth

STATE

Maryland

COUNTY

Allegany

3 CLASSIFICATION

CATEGORY

☐ DISTRICT☒ BUILDING(S)☐ STRUCTURE☐ SITE☐ OBJECT

OWNERSHIP

☐ PUBLIC☒ PRIVATE☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED

STATUS

☒ OCCUPIED☐ UNOCCUPIED☐ WORK IN PROGRESS

ACCESSIBLE

☒ YES RESTRICTED☐ YES UNRESTRICTED☐ NO

PRESENT USE

☐ AGRICULTURE☐ COMMERCIAL☐ EDUCATIONAL☐ ENTERTAINMENT☐ GOVERNMENT☐ INDUSTRIAL☐ MILITARY☐ MUSEUM☐ PARK☒ PRIVATE RESIDENCE☐ RELIGIOUS☐ SCIENTIFIC☐ TRANSPORTATION☐ OTHER**4 OWNER OF PROPERTY**

NAME

Richard Athey

Telephone #:

STREET & NUMBER

Rt. 1

CITY, TOWN

Paw Paw

☐ VICINITY OF

STATE, zip code

W. Virginia, 25434

5 LOCATION OF LEGAL DESCRIPTIONCOURTHOUSE,
REGISTRY OF DEEDS, ETC.

Allegany County Courthouse

Liber #: 453

Folio #: 673

STREET & NUMBER

30 Washington Street

CITY, TOWN

Cumberland

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION**CONDITION**☐ EXCELLENT☐ GOOD☒ FAIR☐ DETERIORATED☐ RUINS☐ UNEXPOSED**CHECK ONE**☐ UNALTERED☒ ALTERED**CHECK ONE**☒ ORIGINAL SITE☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Athey Frame House is located north of Route 51 between Thomas Road and Burslane Run Road.

The original building is a two story, three bays wide structure. A gabled frame addition is on the northern facade. Wall construction is of wide vertical planks. Both the original and addition are covered with large insul shingles.

The building rests on stone pillars at the corners. The roof is gable flank covered with ribbed tin. Eaves consist of an overhanging cornice and soffit. Two brick chimneys on the original are located flush end. Two concrete block chimneys are on the addition, one is outside end, the other on the interior.

Windows of the house are nailed, 6/6 light, double hung, two wooden sash, plain wooden frame, wooden slipsills. The main entrance in the center of the southern facade has three panels, vertical boards, and one light.

On the south a two tiered porch, partially enclosed on the second floor has six chamfered wooden posts.

CONTINUE ON SEPARATE SHEET IF NECESSARY

PERIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW				
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION		
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE		
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE		
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN		
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER		
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION		
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)		
		<input type="checkbox"/> INVENTION				

SPECIFIC DATES Latter half 19th Century BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Athey Frame House was a typical rural farm dwelling found in southeastern Allegany County. The house represents a transition in architecture for the Keifers area because it has stone pillars in the corners like the log houses in the area; yet it is a frame house.

The farmer who built this house and who farmed the property was part of a county-wide participation in agriculture during the latter quarter of the 19th century. "Wheat, oats, potatoes, and corn were the main crops, and most farming was done in the valleys and on low adjacent hills."¹

The house stands as a reminder of a way of life no longer experienced in Allegany County.

1. Harry Stegmaier, Jr. et al. Allegany County- A History (Parsons, West Virginia: McClain Printing Co., 1976) p. 213.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Stegmaier, Harry et al. Allegany County- A History Parsons, West Virginia: McClain Printing Co., 1976.

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 10 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

David A. Dorsey and Shara Goodwin

ORGANIZATION

Allegany County Historic Sites Survey

DATE

STREET & NUMBER

3-33 Pershing Street

TELEPHONE
777-5944

CITY OR TOWN

Cumberland

STATE
Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

INVENTORY NO: AL-I-C-017DATE: 7/7/78REMODELING: Drastic, moderate, minorNAME OF PROPERTY: Athey Frame HouseLOCATION OF PROPERTY: North of Rt. 51 between Burslane Run and Thomas RoadsDIRECTION DWELLING FACES: SouthNAME OF OWNER: Richard AtheyADDRESS: Rt. 1Paw Paw, W. Virginia 26434STORIES: 1() 2(☒) 3() 4() 5() 6() BAYS: 1() 2() 3(☒) 4() 5() 6() 7() ()WINGS, ADDITIONS: gabled frame on NorthDWELLING SHAPE: (square, cross, rectangular)WALL CONSTRUCTION:Wide pine planks

- (☒) FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?)
() BRICK: Bond type - common, English, Flemish. Sketch variants.
() STONE: Bond type - rubble, ashlar (random or regular), quoins-plain, rusticated
() LOG
(☒) OTHER: Coverings Insul shingles

WALL FEATURES: Belt Course, Pilasters, OthersFOUNDATIONS: High, Low, Brick, Stone None - stone pillars on cornersWATER TABLE: None, Plain, Beveled, Moulded BrickWINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6(☒) 9/6() 9/9() other()
pegged() nailed(☒) wide() narrow() mitred() pediment()ENTRANCE, DOORS: LOCATION: Center of southern facade - one lightHARDWARE: original() replaced()

FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN

3 Paneled, Vertical, Horizontal Boards

Box

CORNICE, BARGE, EAVES: (crown, fascia, soffit, bed)original() replaced(☒) rafter ends, modillions, dentils, frieze, architraveROOF: Gable front, Gable flank, Hip, Shed, Mansard, Gambrel, Flat, Dormers #MATERIAL: wood shingles, slate, (tin) asphalt; original() replaced()
(Ribbed)PORCHES: SHAPE OF ROOF - shed() hip() gable() On south, two tiered partially enclosed on
second story - six chamferedCHIMNEYS: Number: 2 Brick(☒) Stone() Corbeled() original(☒) replaced()
Location: Flush end(☒) Inside end() Outside end() Central() Interior()
Two concrete block chimneys on additionARCHES: Door & Windows: Keystone, Flat, Segmental, SemicircularCOMMENTS:USE: ResidenceSIGNIFICANCE: Architecture

DATE CONSTRUCTED: _____

CONDITION: Poor

FLOOR PLAN:

- () CENTRAL HALL: Two rooms, each side; double parlor, one side
- () SIDE HALL: One room deep, two rooms deep
- () IRREGULAR

STAIRWAYS:

- () ENCLOSED: Single flight, two flights with landing
- () OPEN: Single flight, two flights - one landing, three flights - two landings
- () DOG-LEG
- () DOG-LEG with WINDERS
- () SPIRAL
- () ROUNDED
- () SYMMETRICAL DIVIDED FLIGHTS

WALL FINISH:

- () PLASTER
- () paneled: original; replaced
- () BOARD PARTITION: baseboard, cornice, chair rail, wainscot

FIREPLACES:

NUMBER _____

LOCATION: parallel to walls, diagonal

MANTELS: wood mouldings, pilasters, columns, masonry, marble

DOORS: paneled, board and batten, flush


HARDWARE: original; replaced

DOOR & WINDOW TRIM:

- () PLAIN
- () ARCHITRAVE
- () SYMMETRIC with CORNER BLOCKS
- () FLUTED
- () FLUTED with CORNER BLOCKS
- () ARCHED OPENINGS: elliptical, tudor

NOTES:

AL-1-C-017
ATHEY FRAME HOUSE
OFF RT. 51, KEIFERS, MD.
USGS PAW PAW QUAD
1950





AL-1-C-017

Atthey Frame House

Rt. 51 Keifers, Md.

7/7/78

DAVID A. Dorsey

Northwest



AL-1-C-017

Athey Frame House

Rt. 51 Keifers, MA

DAVID A. Dorsey

7/7/78

southeast